

AMS02-TCS

Doc.Nº: NCR-TCS-CGS-C-013

N C Rev.: 1

Date: 08/09/09

MANCE REPORT

ref Page 1 of 3 attach: 1

2 NCR Title: RAM and WAKE Radiators edges covering										
		odel 6	Subsystem 7	Procedure/Work Item Nº						
IDENTIFICATION		M S	M & T	rooddalarffolk Rolli IV						
	AIDC 1/008/08/0 F	IVI	RADIATORS	1						
	8 NC ITEM Identification 9 Drawing Nº. Rev.	10 P.N. / C.I.		11 Serial Nº						
	RAM RADIATOR ASSY 21-AMS-000.00.00 B	21-AMS.000.	New York	01						
	WAKE RADIATOR ASSY 22-AMS-000.00.00 C	ADIATORAGOT								
	(AFE for CGS)									
	12 Next Higher Unit Id.	14 P.N. / C.I.	Nº	15 Serial Nº.						
	3			N.A.						
	N.A.	N.A.		N.A.						
	16 NON CONFORMANCE Detected During:	NON CONFORMANCE Detected During:								
	RECEIVING INSP. MANUFACT. ASSEMBLY/INTEGRATION X FINAL INSPECTION TEST OTHER									
z	17 Initiator, Dept., Date, Signature L. Cremonesi QA 08.09.2									
RIPTION	18 Description of NON CONFORMANCE	/	19 Requ	irements violated						
-F										
O	Theedge radius of the Main RAM and WAKE Ra	diators is n	ot in							
ВES	accordance with NSTS 0700 App.7 Table 11.2 -11	а								
	(see next page)									
1										
			21 Verific	ations						
	20 INTERNAL NRB Dispositions:		21 Verific	ations						
1	The recovery agreed solution is : a) to remove the white paint from the radiator edges									
١	a) to remove the white paint from the radiator edge.b) to clean the surfaces	-								
S Z										
SITION										
0 8 1		See next page for details 22 Suspected cause of NC: HANDLING TRANSPORTATION TEST EQUIPMENT TOOLS SW DESIGN X								
SP	22 Suspected cause of NC:									
_	OPERATOR/PROCEDURE ERROR									
R B	23 Classification Corrective/Preventive Actions:									
Z	125 REQUEST FOR WAIVER 20 Analysis Ke	27 Oth	Other related documents:							
N A L	YES NO X Nº YES NO X Nº									
		30 P.M.	30	31 C.C.						
IN TER	Department: 28 P.A. 29 Syst. Engineering 3			C. Cinquepalmi						
=		M. Olivier								
1	Signature:	M. Q.C.		e, eye.						
	Date: 08.09.2003 09.09.7009	03.04.10	003	10:09:09						
	32 CUSTOMER/HIGHER LEVEL CONTRACTOR NRB Dispositions (Class Major Only): 21 Verifications									
급										
LEVI	SPOSITION									
7										
HER										
0 0	33 Finally determined Cause of NC September 234 Corrective/Preventive Actions:									
ER/HI	Z		00.							
2	0			E OUT CERTIFICATION						
0	Department:		CGS PA/	QA PA/QA Stamp						
) c	Rame.									
O	Z Signature:									
	Date:	non-reservation and an experience of the companion of the								
	puio,	THE RESERVE THE PARTY OF THE PA	THE RESERVE OF THE PARTY OF THE	the state of the s						



AMS02-TCS

Doc.Nº: NCR-TCS-CGS-C-013

N C Rev · 1

Date: 08/09/09

							R	Nev I	
CARLO GAVAZZI SPACE SpA	NON CO	NFO	RMA	NCE	RE	PORT	ref	Page 2	of 3 attach: 1
	37	COI	NTIN	UATI	ON SI	HEET			
SUSPECTED CAUSE OF NC	INTERNAL NRB	ISPOSIT	ION	DI	ESCRIPTI	ON OF NC			21 Verifications
FINALLY DETECTED CAUSE	CUSTOMER NRB	DISPOS	ITION	C	ORRECT/	PREVENT. ACTI	ONS		
REQUIREMENTS VIOLATED									
J									
TABLE II.2-IIa EDGE, CORNER, AND PROTRUSION CRITERIA- EDGE AND IN-PLANE CORNER RADII'									
Application	n	Radius			Remarks Figure		Figure		
				in.	nner mm			II.2-5 Referenced	
		0.25 0.12	6.4 3.0	0.12 0.06	3.0 1.5	Preferred Minimum			
(b) Exposed corners:		0.50	13.0	_	_	Minimum		(a)	
	thick or greater	0.04	1.0	-	-			(b)	
(3)	(0.5 to 2.0 mm) thick less than 0.02	Full Ra	adius	-	-			(c)	
	in. (0.5 mm) thick	Rolled	or Cur	fed				(d)	
other small hardware	operated by the	0.04	1.0	-	-	Minimum required to prevent glove snagging	e) -	
approximately 3/16 in toggle switches, circ connectors, latches,	n. (4.8 mm)) on uit breakers, and other	0.04	1.0	-	-	Absolute minimum unless protruding corner is greater than 120°		^	N N
AIDC has fold EITHER a 45° x 0.3 m	chamfer should be s lowed an interr am chamfer OR	nal sta	i to api andar et rad	proxima d (MN lius oi	M-107,	which res	desc	ribed above.	
	Application (a) Openings, panels, conference (comer radii in plane) (b) Exposed corners: (c) Exposed edges: (1) (d) Flanges, latches, conference small hardware pressurized-gloved hardware pressurized switches, circum connectors, latches, manipulative devices (e) Small protrusions (lest approximately 3/16 in toggle switches, circum connectors, latches, manipulative devices (former radius. The width of connectors and the width of connectors are the width of connectors a	SUSPECTED CAUSE OF NC INTERNAL NRB DE CUSTOMER NR DE CUSTOMER NA DE CUST	SUSPECTED CAUSE OF NC INTERNAL NRB DISPOSE FINALLY DETECTED CAUSE CUSTOMER NRB DISPOSE REQUIREMENTS VIOLATED TABLE II.2-IIa EDGE, CORNER, EDGE AND IN-PLANI Application (a) Openings, panels, covers (comer radii in plane of panel) (b) Exposed comers: (c) Exposed edges: (1) 0.08 in. (2.0 mm) thick or greater (2) 0.02 to 0.08 in. (0.5 to 2.0 mm) thick (3) less than 0.02 in. (0.5 mm) thick (3) less than 0.02 in. (0.5 mm) thick (4.8 mm)) on toggle switches, controls, hinges, and other small hardware operated by the pressurized-gloved hand (e) Small protrusions (less than approximately 3/16 in. (4.8 mm)) on toggle switches, circuit breakers, connectors, latches, and other manipulative devices A 45° chamfer by 0.06 in. (1.5 mm) (minimum) with scorner radius. The width of chamfer should be selected at the corner radius. The width of chamfer should be selected. AIDC has followed an internal state at the corner radius. The width of chamfer should be selected.	SUSPECTED CAUSE OF NC INTERNAL NRB DISPOSITION FINALLY DETECTED CAUSE CUSTOMER NRB DISPOSITION TABLE II.2-IIa EDGE, CORNER, AND P EDGE AND IN-PLANE COR Application Ra Outer in. mm (a) Openings, panels, covers (comer radii in plane of panel) 0.25 6.4 0.12 3.0 (b) Exposed comers: 0.50 13.0 (c) Exposed edges: (1) 0.08 in. (2.0 mm) thick or greater (2) 0.02 to 0.08 in. (0.5 to 2.0 mm) thick (3) less than 0.02 in. (0.5 mm) thick (3) less than 0.02 in. (0.5 mm) thick Rolled or Cur (d) Flanges, latches, controls, hinges, and other small hardware operated by the pressurized-gloved hand (e) Small protrusions (less than approximately 3/16 in. (4.8 mm)) on toggle switches, circuit breakers, connectors, latches, and other manipulative devices A 45° chamfer by 0.06 in. (1.5 mm) (minimum) with smooth corner radius. The width of chamfer should be selected to applications of the corner of th	SUSPECTED CAUSE OF NC INTERNAL NRB DISPOSITION DISPOSITION CONTROL INTERNAL NRB DISPOSITION CONTROL	SUSPECTED CAUSE OF NC INTERNAL NRB DISPOSITION DESCRIPTION CORRECT/ FINALLY DETECTED CAUSE CUSTOMER NRB DISPOSITION CORRECT/ REQUIREMENTS VIOLATED TABLE II.2-IIa EDGE, CORNER, AND PROTRUSION-EDGE AND IN-PLANE CORNER RADII' Application Radius Outer Inner in. mm in. mm (a) Openings, panels, covers (comer radii in plane of panel) 0.25 6.4 0.12 3.0 0.06 1.5 (b) Exposed corners: 0.50 13.0 (0.5 to 2.0 mm) thick or greater (2) 0.02 to 0.08 in. (0.5 to 2.0 mm) thick (3) less than 0.02 in. (0.5 mm) thick Rolled or Curled (d) Flanges, latches, controls, hinges, and other small hardware operated by the pressurized-gloved hand 0.04 1.0 (e) Small protrusions (less than approximately 3/16 in. (4.8 mm)) on toggle switches, circuit breakers, connectors, latches, and other manipulative devices A 45° chamfer by 0.06 in. (1.5 mm) (minimum) with smooth broken edges corner radius. The width of chamfer should be selected to approximate the internal standard (MM-107, EITHER a 45° x 0.3 mm chamfer OR a fillet radius of 0.3 m	SUSPECTED CAUSE OF NC INTERNAL NRB DISPOSITION DESCRIPTION OF NC CUSTOMER NRB DISPOSITION CORRECT/PREVENT. ACTIVITY DETECTED CAUSE CUSTOMER NRB DISPOSITION CRITERIA-EDGE AND IN-PLANE CORNER RADII' Application Radius Remarks Outer Inner In	ALDC has followed an internal standard (MM-107) which results ISUSPECTED CAUSE OF NC INTERNAL NRB DISPOSITION DESCRIPTION OF NC CORRECT/PREVENT. ACTIONS INTERNAL NRB DISPOSITION CORRECT/PREVENT. ACTIONS REQUIREMENTS VIOLATED TABLE II.2-IIa EDGE, CORNER, AND PROTRUSION CRITERIA-EDGE AND IN-PLANE CORNER RADII* Application Radius Remarks Outer Inner in. mm in. mm	SUSPECTED CAUSE OF NC



AMS02-TCS

Doc.Nº: NCR-TCS-CGS-C-013

N C Rev.: 1

Date: 08/09/09

		R						
CARLO GAVAZZI SPACE SpA	NON CONFORMANCE REPORT	ref	Page	3	of 3	attach	n: 1	
X SUSPECTED CAUSE OF NC	INTERNAL NRB DISPOSITION DESCRIPTION OF NC			2	1 Veri	ifications		
FINALLY DETECTED CAUSE	CUSTOMER NRB DISPOSITION CORRECT/PREVENT. ACT	IONS						
REQUIREMENTS VIOLATED								
INTERNAL DISPOSIT	ION							
a) White Paint Remov	val							
The paint has to be NCR-TCS-CGS-C-010 15 mm (maximum) from Step 4 of the instruction be performed because Verify if in some are restore it by brush.	ot							
	lean the areas with the paint removed and to to remove any residue before the tape app							
c) Apply the following Silver Teflon tape along the radiator edges : SHELDAHL G4019; CVLY; TEFLON; 5.0 MIL; SILVER / INC; 966, PERF, 2.5 "; 108 ' ROLL According to CGS procedure GD-WI-CGS-017								
On the radiative si than 1mm from th On the Radiators	,							
the holes which	"							
are treated with Alo								
Moreover do not co								

Procédure particulière Décapage P/D/005 - Révision 1 10.07.2007

Objet:

Stripping of parts treated with SG121FD paint.

CONCERNED PARTS

. Every support.

Diffusion:

(Interne) PDF réseau

(Externe)

PROCESS

- > After customer approval.
- 1) Close up every holes.
- 2) Remove the SG121FD paint mechanicaly with the help of a woodstick and a plastic wedge.

 Bo very carefuly with fragile surfaces as kapton, gold treated.

Rédaction & approbation : Responsable Application

Be very carefuly with fragile surfaces as kapton, gold treated surface...

- 3) Clean the stripped surface with the help of a moisten pad with Flugene 113 or Forane 141b.
- 4) Unpolish the surface with the help of a "PRIMEX" pad ref. NZ089 or equivalent,

5) Clean finally with acetone and Flugene 113 or Forane 141b.

Approbation : Responsable Qualité

- to improve the adhesion of future PSI or PSW primer .
- 6) Unmask the protected areas.

NOTA:

It is very difficult to strip completly PSX or PSW primers.

Historique des modifications

Description succincte


Création	0	
Up to date with PSX Primer in nota part.	1	

Aumer 1 to Ner-Tes-665-6-213

Procédure particulière Décapage P/D/005 - Révision 1 10.07.2007

ANNEXE 1: P/C/008 - Rév. 2

Eprouvette traitée avec PSX + SG121FD ALCATEL ALENIA SPACE



Zone peinte

Zone d'épargne pour bridage dans conteneur